



# SERVICE BULLETIN

|                             |                         |                           |
|-----------------------------|-------------------------|---------------------------|
| Classification:<br>BR96-001 | Reference:<br>NTB96-015 | Date:<br>February 7, 1996 |
|-----------------------------|-------------------------|---------------------------|

## 1995-96 MAXIMA BRAKE SQUEAK/SQUEAL NOISE WHEN COLD

**APPLIED VEHICLE:** 1995-96 Maxima (A32)  
**APPLIED DATES:** For front brakes, vehicles built before July 28, 1995  
For rear brakes, vehicles built before August 30, 1995

### SERVICE INFORMATION

An occasional squeak/squeal brake noise may occur on some Maxima's when the brakes are cold (first few applications). To correct this condition, countermeasures have been developed for the front and rear brake pads and the front brake pad shims.

### SERVICE PROCEDURE

Verify the condition and location (front or rear) at which the noise occurs. If the squeak/squeal noise occurs under cold braking conditions, install the countermeasure parts listed on the next page.

.....  
Index # 047485  
.....

## PARTS INFORMATION

| DESCRIPTION              | PART #/PFP  | QUANTITY |
|--------------------------|-------------|----------|
| Front Brake Pad Kit      | 41060-40U92 | 1        |
| Front Brake Hardware Kit | 41080-40U25 | 1        |
| Rear Brake Pad Kit       | 44060-31U92 | 1        |

## CLAIMS INFORMATION

### Front Brake Pad Replacement <sup>5</sup>

| OPERATION                                      | OP CODE | PNC <sup>1</sup> | SYMPTOM | DIAGNOSIS | FRT     |
|--|---------|------------------|---------|-----------|---------|
| RPL Front Pad Sets-<br>Both Sides <sup>2</sup> | PB19AA  | 41061            | DD      | 69        | 0.7 hrs |

- NOTE:**
1. New Claims System dealers: Submit a Primary Part claim using P/N 41060-40U92 as the PFP.
  2. Brake rotor turning in combination with pad replacement is **NOT** required for this countermeasure.

### Rear Brake Pad Replacement <sup>5</sup>

| OPERATION                                     | OP CODE | PNC <sup>3</sup> | SYMPTOM | DIAGNOSIS | FRT     |
|---|---------|------------------|---------|-----------|---------|
| RPL Rear Pad Sets-<br>Both Sides <sup>4</sup> | PD19AA  | 44061            | DD      | 69        | 0.7 hrs |

- NOTE:**
3. New Claims System dealers: Submit a Primary Part claim using P/N 41060-31U92 as the PFP.
  4. Brake rotor turning in combination with pad replacement is **NOT** required for this countermeasure.
  5. If both front and rear brake pads are replaced, "old" claims system dealers should put both Op Codes on the same claim using PNC 41060. New Claims System dealers should submit a separate line for each PFP.