



NISSAN MOTOR CORPORATION IN U.S.A.

Post Office Box 191
Gardena, California 90248
Telephone: (310) 532-3111

M

TECHNICAL DATABASE INFORMATION

Record ID: FC0010062	Source Reference Number: NMC	Classification: JAN '95
Subject: A/T SLIPS IN R	Entered On: 01/09/95	
Model Line: ALT MAX QST	Model Year: ALL	

Technical Information Abstract:

SYMPTOMS: TRANSMISSION SLIPS IN REVERSE AND HAS NO ENGINE BRAKING IN D1 RANGE AFTER OVERHAUL. CONDITION MAY NOT HAVE EXISTED PREVIOUS TO SERVICING.
ALL FO4 EQUIPPED VEHICLES

FIELD FIX: DURING THE REMOVAL OF THE LOW & REVERSE PISTON ASSEMBLY THE SLEEVE THAT SEALS THE TUBE TO THE RETAINER CAN BE DAMAGED. IF THIS SEAL IS DAMAGED AND NOT REPLACED INTERNAL PRESSURE LEAKAGE MAY OCCUR. REFER TO THE APPROPRIATE SERVICE MANUAL IN THE AT SECTION, PORTION 'ASSEMBLY 3', FOR TUBE AND SLEEVE LOCATION.

.....
Index # **041944**
.....