



# SERVICE ADVISORY



Classification: HA95-01	Section: Air Conditioning	Models: 1995 Maxima (A32)
Reference: SERVICE ADVISORY NTB95-004		Date: January 25, 1995

## 1995 MAXIMA A/C SPECIFICATION

### SERVICE INFORMATION

The 1995 Maxima Service Manual, April 95 edition, on page HA 138 and on the quick reference Chart located on the inside back cover show an incorrect amount of refrigerant capacity. The blue air conditioner specification label under the hood of the vehicle lists the correct refrigerant capacity of **1.43 +/- 0.11 lbs.** Use the under hood label for the correct capacity when performing any air conditioner service.

.....  
Index # **040989**  
.....

NISSAN MOTOR CORPORATION, U.S.A.  
Technical Communications Department